

Technical inspection

Nr. 1713TT07574

für:

Kalmar DRF450-65S5X
Serial-no: T34113.1268



Hansjochen Schweigert

Von der Handwerkskammer Lüneburg-Stade-Braunschweig
öffentlich bestellter und vereidigter Sachverständiger
für das KFZ-Handwerk



Altmitglied im Bundesverband der freiberuflichen und unabhängigen
Sachverständigen für das Kraftfahrzeugwesen e.V.



Bewertungspartner der Firma Classic Data
Bewertungen von Oldtimern, Youngtimern und Exoten

René Schweigert

Kfz-Meister



Thorsten Tattenberg

Von der IQ-Zert zertifizierter Sachverständiger für Kraftfahrzeugschäden
und -bewertungen



Mitglied im Bundesverband der freiberuflichen und unabhängigen
Sachverständigen für das Kraftfahrzeugwesen e.V.

Vehicle inspection

We herewith state the inspection of a secondhand container-reachstacker

make:	Kalmar		
model:	DRF450-65S5X		
serial-no:	T34113.1268		
year of construction:	2007		
country of origin:	Sweden		
capacity:	45 tons under spreader		
tires:	3x Simex 1x Bridgestone	18.00-33	80 % on drive axle
	2x. Continental	18.00-33	80 % on steering axle
running hours :	20908,0		
cabin :	sliding cabin for better view		
mast:	duplex telescopic boom		
Location position:	Hamburg, 29.05.2017		

Capacity test: laden 20' and 40' containers have been lifted without any problem

Overload control: is working well

Topspreader: telescopic for 20-40' containers is working well – no oil leaks

Engine & Gearbox: both are in good running condition without oil leaks

Brake test: was made with good result

Hydraulic System: is working well without any faults and without oil leaks

The machine is in good condition without leakage. The machine is clean and in a very neat used condition

Exterior:

Body and equipment (all available) with visible traces of use (according to age)

Functional check (mechanics) of doors, hoods and flaps without deficiency

All windows without deficiency

Rims and front tires without damage

Front and rear light without deficiency

Interior:

Instruments and control device without detectable defect

No vehicle pollution

Switches and levers without deficiency

Ventilation / heating without noticeable deficiency

All panels, floor and ceiling with visible traces of use (according to age)

Seat functions without deficiencies, seats with visible traces of use (according to age)

Vehicle bottom:

All steering and axle parts without detectable deficiency

Exhaust system is tight the rear muffler it has rust and without recognizable defects

Engine, gearbox and axles without recognizable defects

Engine compartment:

Engine oil level in the tolerance range

Cooling system without noticeable damage

Test drive:

Transmission (automatic, double clutch) without complaint


Brake test without deficiencies

The tracking accuracy was good

No atypical sounds audible

The assessment was prepared neutrally and independently and to the best of our knowledge.

Hamburg, 01.06.2017


Thorsten Tattenberg

Certified by IQ-Cert for
Motor vehicle damage and ratings

